

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2009 Levee Inspection Results

Reclamation District No. 0784

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Reclamation District No. 0784

Waterway		Bank	Unit Miles
Unit No. 01 Yuba River		Left	2.20

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/29/2009 - 4/29/2009			
DWR Inspector	Clay Thomas			
Accompanied By	Steve Fordice RD-784			

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0784

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yuba River	Left	2.20	04/29/2009 04/29/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.03	2.03	Earthen Levee	Encroachments	CR	C	Equipment Inspector Comments: segment 3 levee repair in process	39.128159 ° -121.587086 °	39.128159 ° -121.587086 °		1
2	2.13	2.13	Earthen Levee	Encroachments	CR	C	Equipment Inspector Comments: levee repair	39.127028 ° -121.588046 °	39.127028 ° -121.588046 °		2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Reclamation District No. 0784

Waterway				Bank	Unit Miles
Unit No. 02 Feather River				Left	13.60

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/29/2009 - 4/29/2009			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0784

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Feather River	Left	13.60	04/29/2009 04/29/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1			Earthen Levee	Encroachments	LS	CO	Inspector Comments: This levee ends at approximate l/m 12.80, levee changed when set back levee was built.	° °	° °		5
2	2.16	2.44	Earthen Levee	Encroachments	CR	C	Equipment Inspector Comments: levee in repair process	39.098473 ° -121.586031 °	39.094577 ° -121.584758 °		6
3	9.89	12.72	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.997067 ° -121.580305 °	38.956823 ° -121.575383 °		8
4	9.89	12.71	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.997062 ° -121.580278 °	38.956980 ° -121.575425 °		7

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Reclamation District No. 0784

Waterway		Bank	Unit Miles
Unit No. 03 Bear River		Right	4.70

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/28/2009 - 4/29/2009			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0784

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 03 Bear River	Right	4.70	04/28/2009 04/29/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.47	3.15	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.971320 ° -121.547073 °	38.974910 ° -121.536110 °		7
2	2.82	2.82	Earthen Levee	Encroachments	CR	PO	Equipment Inspector Comments: hwy 70 new bridge construction	38.974003 ° -121.541910 °	38.974003 ° -121.541910 °		4
3	3.24	4.69	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.974450 ° -121.532567 °	38.985365 ° -121.510768 °		5
4	3.24	4.69	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.974445 ° -121.532562 °	38.985348 ° -121.510748 °		6

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Reclamation District No. 0784

Waterway		Bank	Unit Miles
Unit No. 04 Interceptor Canal		Left	6.30

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/29/2009 - 4/29/2009			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0784

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 04 Interceptor Canal	Left	6.30	04/29/2009 04/29/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	2.42	3.62	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	39.009253 ° -121.541737 °	39.026573 ° -121.542363 °		2
2	3.19	3.58	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.974710 ° -121.535403 °	39.026115 ° -121.542372 °		4
3	3.61	4.88	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	39.026533 ° -121.542272 °	39.044868 ° -121.542415 °		3
4	4.88	5.59	Earthen Levee	Vegetation	LS	C	Control annual grass and weeds on the levee slopes and easements.	39.044807 ° -121.542415 °	39.055144 ° -121.542506 °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Reclamation District No. 0784

Waterway		Bank	Unit Miles
Unit No. 05 Interceptor Canal		Left	4.20

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/28/2009 - 4/28/2009			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0784

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 05 Interceptor Canal	Left	4.20	04/28/2009 04/28/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.01	4.20	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.974698 ° -121.532732 °	39.020548 ° -121.508983 °		8
2	0.01	4.20	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.974698 ° -121.532732 °	39.020548 ° -121.508982 °		7
3	1.08	1.72	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	38.989955 ° -121.535672 °	38.999068 ° -121.537462 °		10
4	2.10	3.06	Earthen Levee	Encroachments	LS	PO	Agricultural Ditch	39.004562 ° -121.538482 °	39.015593 ° -121.528533 °		9
5	3.79	3.79	Earthen Levee	Erosion / Bank Caving	WS	C	Note and monitor erosion site.	39.019236 ° -121.516381 °	39.019236 ° -121.516381 °		6

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Reclamation District No. 0784

Waterway		Bank	Unit Miles
Unit No. 06 South Dry Creek		Right	0.30

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/28/2009 - 4/28/2009			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0784

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 06 South Dry Creek	Right	0.30	04/28/2009 04/28/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	0.23	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements.	38.985548 ° -121.510548 °	38.987558 ° -121.506602 °		1
2	0.00	0.23	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.985597 ° -121.510515 °	38.987567 ° -121.506605 °		2

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Reclamation District No. 0784

Waterway		Bank	Unit Miles
Unit No. 07 Yuba River		Left	3.90

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/28/2009 - 4/28/2009			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0784

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 07 Yuba River	Left	3.90	04/28/2009 04/28/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	3.91	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: levee mile tool has this as l/m 6.24 it's l/m 3.91	39.134773 ° -121.552087 °	39.165277 ° -121.495265 °		9
2	0.00	3.91	Earthen Levee	Vegetation	LS	M	Control annual grass and weeds on the levee slopes and easements. Inspector Comments: levee mile tool has 3.91 as l/m 6.24	39.134772 ° -121.552088 °	39.165275 ° -121.495312 °		8
3	2.16	2.28	Earthen Levee	Encroachments	WS	PO	Equipment Inspector Comments: equipment has been moved 10-15 feet from levee into DFW.	° °	° °		3
4	2.79	2.79	Earthen Levee	Encroachments	CR	C	Inspector Comments: l/m 1.79 to 3.91 is a patrol road, l/m 1.79 at locator mile 2.79	39.144676 ° -121.523826 °	39.144676 ° -121.523826 °		7
5	3.29	3.29	Earthen Levee	Erosion / Bank Caving	WS	C	Note and monitor erosion site. Inspector Comments: ck levee locator, l/m 3.30, tool has this as l/m 5.23, levee is 3.91 total	39.160679 ° -121.504872 °	39.160679 ° -121.504872 °		5
6	3.30	3.30	Earthen Levee	Erosion / Bank Caving	WS	C	Note and monitor erosion site.	° °	° °		4

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Reclamation District No. 0784

Waterway		Bank	Unit Miles
Unit No. 08 Three Rivers			

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/29/2009 - 4/29/2009			
DWR Inspector	Clay Thomas			
Accompanied By				

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports
3310 El Camino Avenue, Room LL-30
Sacramento, CA 95821-9000.

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2009

Reclamation District No. 0784

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 08 Three Rivers			04/29/2009 04/29/2009	Clay Thomas

LMR Line	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Photo	Issue
	Start	End						Start	End		
1	0.00	1.95	Earthen Levee	Crown Surface / Depressions / Rutting	CR		Inspector Comments: New setback levee. Right Bank Bear River, LM 0.00 is at Feather River levee centerline unit 2 approx LM 12.80, Equation: Mile 1.95 on setback levee equals mile 2.43 on RD 784 unit 3, milage runs upstream.	° °	° °		1

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable PO : Partially Obstructing C : Corrected
M : Minimally Acceptable CO : Completely Obstructing
U : Unacceptable N : Not Inspected